

January 29, 2007

REPAIR DISCONTINUANCE NOTIFICATION

Dear JSR Ultrasonics Customer,

Due to the difficulty in sourcing certain electronic components required for repairs, JSR Ultrasonics will discontinue repairs on the following products effective March 31, 2007:

JSR Pulsar-Receivers	JSR Remote Pulsers
DPR002, DPR002-HF/LF, DPR002-S-HF/LF DPR35, DPR35+ DPR35E, DPR35E+, DPR35E-HV DPR35G, DPR35-S DPR50, DPR50+ PR002A PR35, PR35-S PR50	66-601B HF-6.5, HF-9.5, HF-14 HF-A, HF-B UHF-RPPA, UHF-RPPA-S UHF-RPHV-S VHF-1.4, VHF-1.7, VHF-3.0, VHF-5.6

Until further notice, JSR Ultrasonics will continue to certify fully functional instruments.

No response to this notification is required. Please address any concerns you may have via email to sales@jsrultrasonics.com.

Thank you.
The Team at JSR Ultrasonics